

## TECHNICAL INFORMATION INDEX

The Technical Information Index (TII) is an index for locating current service information. It is also an index for locating current Reliability and Safety CEM's (denoted by shading). If the information is in the "Combined Service Information Booklet," the TII will indicate "CSI" and the page and item number. If the information is in a current CEM, "CEM" will be indicated in the current publications column and the CEM number under the CEM column.

Abbreviations used in the Technical Information Index:

APM — Adjustment Parts Manual  
CEM — Customer Engineers Memorandum  
CSI — Combined Service Information  
SA — Service Aids

SHP — Shop Manual (F/N Z241-6670)  
SM — Service Manual  
TYP — Type Catalog (F/N S241-5687)

This TII should be filed as the first page of CEM's. This TII includes CEM's through No. 503.

Denotes Current Codes 32 and 33

CEM No.	Current Pub.	Subject	CSI Page/Item
<b>GENERAL</b>			
493 .CEM .		APM Correction — Ribbon Cassette . . . . .	
433 .APM .		Adjustment Parts Manual (241-5939-2) Correction . . . . .	
422 .CEM .		Announcement IBM "Selectric" III Typewriter . . . . .	
496 .CEM .		Announcement — IBM Personal Type- writer Model 831 . . . . .	
	CSI .	Copper Colored Screws . . . . .	1-3
444 .TC .		Custom Keybuttons . . . . .	
85 .CSI .		Dynamic Half Cycle Tool . . . . .	1-8
	CSI .	Front Feed Roll Adjusting Screw Wrench . . . . .	1-2
	CSI .	Installing Small Nuts On Splined Screws . . . . .	1-4
	CSI .	Keybutton Removal Tool . . . . .	1-7
	CSI .	Keylever Pawl Restoring Springs Installation . . . . .	24-4
501 .CEM .		Electrical Safety Precautions . . . . .	
418 .CSI .		Motor Label . . . . .	30-1
311 .CSI .		Operational Keybuttons — Damaged . . . . .	1-1
462 .PNM .		PN/PL Correction . . . . .	
90 .CSI .		Power Cleaner — Overheating . . . . .	1-6
381 .SM .		Rotate Selection Adjusting Tool (P/N 9900633) . . . . .	
311 .CSI .		Skirt Clearance Adjustment — Accessibility . . . . .	1-5
114 .CSI .		Splined Wrenches Brittle . . . . .	1-10
427 .CEM .		Stroke Counters — SER Only . . . . .	
92 .CSI .		Tilt Detent — Adjusting Wrench . . . . .	1-9
311 .CSI .		Tilt Home/Skirt Clearance Adjustment . . . . .	2-2
<b>APPLICATIONS</b>			
467 .CEM .		Court Reporter Element — Underscore . . . . .	
178 .CSI .		Type Element — Bookface Academic . . . . .	2-4
	CSI .	Type Element — Dual Gothic 72 . . . . .	2-2
	CSI .	Type Element — 1428 Optical Scanning . . . . .	2-3
	CSI .	Type Element — Orator . . . . .	2-1
<b>BACKSPACE</b>			
466 .CEM .		APM Correction — Backspace . . . . .	
426 .CEM .		Backspace Driver Mtg. Stud — B/M . . . . .	
249 .APM .		Bellcrank Downstop (RB) — Redesigned . . . . .	
144 .APM .		Cable Clamp (RB) — Locating Lug . . . . .	
302 .CSI .		Cam Follower, SP — Strengthened . . . . .	3-6
	CSI .	Cam Pawl Wear — Space/Backspace . . . . .	2-5
188 .CSI .		Drive Link Spacer — Binding . . . . .	3-4
383 .CEM .		Escapement Rack — Soft . . . . .	21-4
172 .APM .		Half Backspace — "A" Frame . . . . .	
265 .APM .		Half Backspace — Level 2 . . . . .	
272 .CSI .		Half Backspace — Level 3 . . . . .	3-5
202 .CSI .		Interlock Shaft — Redesigned . . . . .	3-3
341 .APM .		Interlock Shaft — Redesigned . . . . .	
	CSI .	Latch Spring Installation . . . . .	31-6

CEM No.	Current Pub.	Subject	CSI Page/Item
91 .APM .		Nine Pitch 7X1 — Parts . . . . .	
	CSI .	Pawl Replacement Procedure . . . . .	17-2
212 .CSI .		Pitch Change Cable Routing . . . . .	2-6
458 .CSI .		Rotary Backspace Bellcrank Stop — Level 1 Field Fix . . . . .	4-2
185 .CSI .		Rotary Backspace Bellcrank Stud . . . . .	2-7
311 .CSI .		Rotary Backspace Drum — Removal . . . . .	3-2
293 .CSI .		Rotary Backspace Drum Wear . . . . .	3-1
140 .APM .		Rotary Backspace — Spring Tension . . . . .	
321 .CSI .		"Selectric" II Typewriter — 9 Pitch . . . . .	4-1
335 .APM .		Single Pitch — Rotary Backspace — New . . . . .	
<b>CARRIER AND ROCKER</b>			
367 .CSI .		Ball Joint (Dog Bone) — Out Of Spec . . . . .	7-5
440 .CSI .		Cable Guide — Redesigned . . . . .	8-2
468 .CEM .		Carrier Bearing — Reference Number Added To APM . . . . .	
320 .CSI .		Carrier Buffer — Field Installed . . . . .	7-3
	CSI .	Carrier Movement — Machine Half Cycled . . . . .	5-6
168 .APM .		Carrier Pointer — Ridged . . . . .	
311 .CSI .		Carrier Replacement — Service Tip . . . . .	5-7
398 .CSI .		Carrier Replacement — Service Tip . . . . .	8-1
80 .APM .		Carrier Shoe — Nonadjustable . . . . .	
315 .CSI .		Correcting Tape Lift — Carrier Bearing Loose . . . . .	6-1
467 .CEM .		Court Reporter Element — Underscore . . . . .	
385 .APM .		Detent Actuating Lever Support Screw — Redesigned . . . . .	
209 .CSI .		Dual Velocity Cable Clip — Installation . . . . .	5-8
223 .CSI .		Head Play Excessive . . . . .	5-3
	CSI .	Impression Variations — Print Cam Follower . . . . .	4-3
	CSI .	Light Characters — Fabric Or Film Ribbon . . . . .	4-5
470 .CSI .		Platen Height Adjustment — Print Quality . . . . .	7-4
	CSI .	Print And Escapement Failures . . . . .	5-1
195 .CSI .		Rotate Alignment Changing — Adjustment Check . . . . .	5-2
256 .APM .		Rotate Detent Guide — Redesigned . . . . .	
	CSI .	Rotate Pulley Setscrew Stripped . . . . .	5-5
	CSI .	Skirt Clearance Adjustment — Accessibility . . . . .	1-5
	CSI .	Skirt Clearance, Loss Of . . . . .	4-4
112 .APM .		Tilt Detent Guide Screw — Shortened . . . . .	
179 .APM .		Tilt Ring — Biased . . . . .	
317 .CSI .		Tilt Ring Pivot Screws — Hex Head . . . . .	7-2
	SM .	Tilt Ring Removal . . . . .	
443 .CSI .		Tilt Rings — Assembled Incorrectly . . . . .	8-4
	CSI .	Tilt Ring Shim Centering . . . . .	5-4
222 .CSI .		Tilt 3 Characters Low . . . . .	4-6
	CSI .	Type Element — Alignment Check . . . . .	6-2
76 .CSI .		Type Element — Latch Spring Breakage . . . . .	6-6
156 .CSI .		Type Element — Lubrication . . . . .	7-1
	CSI .	Type Element — Plating Damage . . . . .	6-5
329 .CSI .		Type Element — Teeth Breakage . . . . .	6-3

CEM No.	Current Pub.	Subject	CSI Page/Item
192 .CSI .		Under Printing — Bookface Academic, Prestige Pica . . . . .	6-4
396 .CSI .		Velocity Lever Asm. . . . .	7-6
<b>CARRIER RETURN</b>			
480 .CEM .		Carrier Return And Express Backspace Shoe Arm — Redesigned . . . . .	
316 .CSI .		Carrier Return/Express Backspace Shoe — Combined . . . . .	10-2
364 .CSI .		Carrier Return Interlock Clip — Redesigned . . . . .	10-3
392 .CSI .		Carrier Return Latch Redesigned . . . . .	11-1
451 .CSI .		Carrier Return Unlatching Link — Interference . . . . .	11-3
428 .CSI .		Carrier Return — Uneven/Sluggish/Jerky . . . . .	11-2
95 .SM .		Cord Replacement Procedure . . . . .	
	CSI .	Cord Wear — Carrier Return . . . . .	9-1
477 .CEM .		CR Unlatching Link — 7X3 An 7X5 — PN/PL Correction . . . . .	
395 .SM .		Dual Transport Conversion . . . . .	
	CSI .	Keylever Pawl Overlapping — Return/Index . . . . .	10-1
TIP .CSI .		Overbank Adjustment — Simplified . . . . .	26-5
60 .CSI .		Latch Overthrow . . . . .	9-4
	CSI .	Partial Return — Space/Return Operation . . . . .	9-5
	CSI .	Partial Return — Torque Bar Clip . . . . .	9-3
88 .CSI .		Pawl Clearance — Loss Of . . . . .	9-9
119 .APM .		Return Latch Shaft Spacer (DP) . . . . .	
181 .APM .		Return Mechanism (SP) — Redesigned . . . . .	
	CSI .	Scraping Noise On Return . . . . .	9-10
241 .CSI .		Shoe Clearance — Excessive . . . . .	9-2
	CSI .	Slow Or Uneven Return . . . . .	9-7
308 .CSI .		Slow Or Uneven Return . . . . .	9-8
228 .APM .		Torque Limiter — Eccentric Stud Eliminated . . . . .	
184 .APM .		Torque Limiter Hub — Hub Lugs Added . . . . .	
	CSI .	Torque Limiter Lubrication . . . . .	32-4
376 .CSI .		Transport Cord Pulley Assemblies — Redesigned . . . . .	49-1
391 .CSI .		Uneven Left Margin . . . . .	26-4
	CSI .	Unlatching Failures . . . . .	9-6
<b>CORRECTING</b>			
250 .APM .		Cardholder, Correcting — Material Changed . . . . .	
230 .APM .		Cardholders Popping Out — Dimples Added . . . . .	
210 .CSI .		Carrier Binds — Tab Or Spacebar . . . . .	11-4
400 .APM .		Correcting Keypoint Interlock — Field Inst. . . . .	
464 .CEM .		Correcting Lift And Feed Actuator Stud . . . . .	
490 .CEM .		Correction Lift Guide Restore Spring— Redesigned . . . . .	
386 .CSI .		Correcting Mechanism FRONT Carrier Support And Torque Bar Asm. Changed From Plastic To Metal . . . . .	13-4
310 .CSI .		Correcting Mechanism — New — FTB . . . . .	13-1

CEM No.	Current Pub.	Subject	CSI Page/Item
315	.CSI	Correcting Tape Lift — Carrier Bearing Loose	6-1
413	.CSI	Correction Tape — Intermittent Feed Failures	13-6
498	CEM	Correction Tape Feed Cam — Defective	
401	.APM	Correcting Tape Feed — B/M	
197	.CSI	Cradle Assembly Binds	12-6
395	.SM	Dual Transport Conversion	
210	.CSI	Incomplete Lift-Off	12-2
261	.CSI	Keylever And Button — Lowered	15-2
216	.APM	Limiting Device — Correctable Film Ribbon Load Lever Spring — Redesigned	
409	.CSI	Paper Bail Arm Spring — Redesigned	36-2
205	.APM	Print Shield — Correcting	
402	.CSI	Ribbon Folding-Wrapping Around Spiked Driver	41-2
	.CSI	Right Hand Dust Cover Retainer Clip	13-5
338	.CSI	Stalling Motors — During Correction	13-2
247	.CSI	Tape Feed Cam — Redesigned	11-4
237	.CSI	Tape Feed — Continuous	12-1
242	.CSI	Tape Feed — Failures	12-4
210	.CSI	Tape Feed — Intermittent Failures	12-2
324	.CSI	Tape Feed — Redesigned	12-5
344	.CSI	Tape Take-Up Spool — Paper Interference	13-3
244	.APM	Torque Bar Collar — Non-FTB	
<b>COVERS AND MOUNTING</b>			
393	.CSI	Acoustical Hood Seal — Redesigned	47-3
97	.APM	Bolt Down Hardware — Theft Deterrent	
495	.CEM	Bottom Cover, New — Plastic	
430	.CSI	Center Cover Bracket — Redesigned	
286	.CSI	Center Cover Clip — Polyester Covers	17-2
157	.APM	Cover Adaptor B/M — To Snap Off Covers	
456	.CEM	Cover — Defective Paint	
245	.CSI	Cover Hinge And Mounting — Redesigned	17-1
417	.APM	Cover Hinge — B/M	
	.CSI	Cover Hinge Screw — Stripped	17-9
	.CSI	Cover Incompatibility — 7X1	17-10
	.CSI	Cover Latch Levers	16-9
	.CSI	Cover Removal — Friction Fit	16-8
253	.APM	Covers — Reinforced Polyester 7X1	
	.CSI	Dust Shield Clip	18-1
103	.APM	Dust Shield Clip — Field Replacement	
407	.CSI	Heat Buildup	15-8
148	.APM	Logo — Double Insulated	
96	.APM	Margin Scale — Numbered By 5's	
	.CSI	Margin Trim — Installation	16-5
	.CSI	Margin Trim — Scratched	16-6
330	.APM	Membrane Support — Foam Rubber	
439	.CSI	Motor Vent Grill — Double Insulation Breaks	15-4
325	.CSI	ON/OFF Button Jammed — Sound Pack	16-3
476	.CEM	Page End Indicators — Removal Of Extension	
171	.APM	Paints Discontinued — Rel Tex	
154	.APM	Paints, New — Willow Green And Classic Blue	
62	.CSI	Paper Table And Margin Scale Graphics	14-1
	.CSI	Service History Insert	14-4
87	.APM	Shock Mounts — Loose — Oversized Available	
196	.APM	Sound Reduction Package FI B/M	
	.CSI	Top Cover Bracket	14-7
339	.CSI	Top Cover Hinge — Redesigned	14-8
475	.CEM	Top Cover Jammed — Sound Reduction Machines	
419	.CSI	Top Cover Latch — Shock Mounts	15-9
348	.CSI	Top Cover Latch — Strengthened	15-2
	.CSI	Top Cover Pin	15-3
326	.CSI	Vent Grills And Platen Knobs — Black	15-1
361	.APM	Vent Grills (7XX)	
133	.APM	Warning Label — Operator	
<b>DEAD KEY</b>			
296	.CSI	Dead Key Cable Breaking — Correcting	16-5
	.CSI	Dead Key Cable — Operational Shaft Wear	16-6
	.CSI	Dead Key, Dead Key Disconnect — Explanation	16-4
26	.APM	Dead Key Disconnect — Adjustment	
102	.APM	Dead Key Disconnect B/M — Field Service	
<b>ESCAPEMENT</b>			
334	.SM	Adjustment Procedure — Escapement	
479	.CEM	Escapement Bracket (RB/SI) Defective	

CEM No.	Current Pub.	Subject	CSI Page/Item
415	.CSI	Escapement Bracket — Washer/Clip Added	49-3
	.CSI	Escapement Failures — Old Machines	17-6
460	.CSI	Escapement Pawl Mounting Stud — Redesigned	19-5
232	.APM	Escapement Rack And Sector Gear — Wear	
383	.CSI	Escapement Racks — Soft	19-4
332	.CSI	Escapement Rail (DP) — Polyester	19-1
	.CSI	Escapement Shaft Bearing Binds	17-4
	.CSI	Pawl Replacement Procedure	17-2
91	.APM	Nine Pitch 7X1 — Parts	
459	.CEM	Pawl Mounting Stud	
137	.APM	Pawl Mounting Stud — Diameter Decreased	
	.CSI	Pawl Spring Replacement	17-3
	.CSI	Pawl Wear — Diagnosis	17-1
136	.APM	Sector Gear And Switch Pitch Lever — Redesigned	
335	.CSI	Single Pitch — Rotary Backspace — New	19-2
159	.CSI	Skipping — Dual Pitch	17-1
83	.CSI	Skipping — New Trigger Mechanism	19-6
276	.CSI	Skipping — Single Pitch	17-1
	.CSI	Space To Print — Service Tips	17-7
346	.CSI	Torque Bar Backup Screw Nut — Eliminated	19-3
284	.APM	Torque Bar Backup Stud — Center	
243	.APM	Torque Bar Backup Stud — Left Side	
199	.APM	Torque Bar Backup Stud, Pawl Mounting Stud — New	
66	.APM	Trigger Assembly — Simplified	
	.CSI	Trigger Height — Varies	17-5
219	.APM	Trigger Mounting Stud — Field Replaceable	
<b>FRAME</b>			
92	.CSI	Center Bearing — Replacement Procedures	20-1
474	.CEM	Selectric III Incorrect Machine Type Code	
<b>INDEX</b>			
295	.APM	Adjustment Procedure	
473	.CEM	Detent Arm And Roller 54T — Redesigned	
314	.CSI	Double Index Mechanism	21-3
365	.CSI	Double Index — Plant Installed	22-3
155	.APM	54T Conversion B/M	
503	.CEM	Index Conversion B/M — 54 To 27 Tooth	
358	.APM	Index Conversion B/M — 54 To 27 Tooth	
262	.CSI	Index Failures	20-2
356	.APM	Index Overthrow Stop — Redesigned	
494	.CEM	Index Link — Redesigned	
414	.CSI	Index Pawl And Ratchet Alignment	20-3
298	.APM	Index Pawl Assembly Stud — Field Replacement	
333	.CSI	Lower Index "C" Clip — Redesigned	22-1
110	.APM	Platen Detent, 54T — Redesigned	
	.CSI	Platen Detent Identification	21-2
453	.CEM	Platen Detent — Interference	
448	.CSI	Stop — Selector Cam Lever Mounting Bracket — "A" Frame with Double Index	22-4
341	.CSI	Transfer Bellcrank — Redesigned	22-2
307	.CSI	Transfer Bellcrank Stop Lug — Wear	20-4
215	.CSI	2 — 2 1/2 — 3 Lines Per Inch — SER	21-1
	.CSI	Weak Index	20-2
<b>KEYBOARD</b>			
364	.CSI	Carrier Return Interlock Clip — Redesigned	10-3
	.CSI	Compensator Tube Adjustments — Old Level	24-1
89	.APM	Compensator Tube End Plug — Wedge Type	
444	.TC	Custom Keybuttons	
81	.APM	Cycle Clutch Bail Dampers — Spring	
	.SM	Cycle Clutch Keeper Adjustments	
69	.CSI	Cycle Clutch Latch Restoring Springs	23-6
	.CSI	Cycle Clutch Link Binds	23-7
452	.CSI	Dual Impression Cam/Mounting Bracket — Interference	24-6
	.CSI	Flicking	23-2
	.CSI	Interposer Restoring Spring — Replacement	23-9
	.CSI	Interposer Sliding Off Filter Shaft	24-2
484	.CEM	Keyboard Damper Spring — Changed	
	.CSI	Keyboard Insulation	24-5
266	.SM	Keyboard Out Of Position	
153	.APM	Keyboard Side Frame — Redesigned	
478	.CEM	Keyboards Touch Problems	
	.CSI	Keybutton Removal Tool	1-7
	.SM	Keybutton Replacement	
	.CSI	Keylever Forming Tool Hooverometer	23-12
	.CSI	Keylever Pawl Breakage — Auto Operation	23-11
487	.CEM	Keylever Pawl B/M	

CEM No.	Current Pub.	Subject	CSI Page/Item
	.CSI	Keylever Pawl Restoring Springs Installation	24-4
	.SM	Keylever Removal	
	.CSI	Keylever Restoring Spring — Lubrication	23-10
	.CSI	Keylever Side Play	23-3
	.CSI	Keylever Springs — Replacement	23-13
	.CSI	Keylever Tension Springs — Installation	23-8
47	.CSI	Loose Keyboards	23-5
	.CSI	Manual Velocity Control — Binds	25-3
	.CSI	Operational Keybuttons — Damaged	1-1
446	.CSI	Replacing Broken "Selectric" Latch Links	45-10
382	.CSI	Repeat Row Four Keylever — Plant Installed	25-2
463	.CEM	Screws Changed In Cycle Clutch Bracket	25-1
152	.APM	Selector Latch Interposer And Bail — Redesigned	
	.SM	Slow Or Hard Keyboards	
73	.APM	Spacebar — Spring Loaded	
	.CSI	Touch Problems	23-1
277	.CSI	Touch Problems — Oversized Compensator Tube	24-3
<b>MARGIN, LINELOCK AND BELL</b>			
	.CSI	Bell Mounting Stud — Field Replacement	25-8
449	.CEM	Bellringer Bellcrank — Redesigned	27-3
387	.CSI	Bellringer Bellcrank — Unwanted Correction	26-3
383	.CSI	Escapement Rack — Soft	19-4
173	.APM	Margin Assembly, RH (DP) — Roller	
254	.APM	Margin Lever (8XX And 7XX) — Redesigned	
	.CSI	Margin Lever Replacement	25-6
	.CSI	Margin Pin And Slider Removal And Installation	25-7
411	.CSI	Margin Rack Gear	27-2
408	.CSI	Margin Rack — Single Pitch (Rotary B/S)	27-1
233	.APM	Margin Rack (SP) — Redesigned	
343	.CSI	Margin Rack Toggle Spring — Removed	26-1
469	.CEM	Margin Set Levers	
194	.CSI	Margin Sliders Binding	25-3
	.CSI	Margin Stops Binding	25-4
91	.APM	Nine Pitch 7X1 — Parts	
TIP	.CSI	Overbank Adjustment — Simplified	26-5
384	.CSI	Pointers, "Selectric" II — Redesigned	26-2
136	.APM	Sector Gear And Switch Pitch Lever — Redesigned	
	.CSI	Switch Pitch Gear Adjustment — Margin	25-5
472	.CEM	Transformer Motor — "Selectric" III	
391	.CSI	Uneven Left Margin	26-4
<b>MOTOR AND DRIVE</b>			
186	.CSI	Capacitor Boot — "A" Frame	29-2
455	.CEM	CE Safety Exposure	
213	.CSI	Double Insulation — Motor Vent Grill	15-4
176	.CSI	Double Insulation — Recon "Selectrics"	29-3
246	.APM	Drive Belt — Fiberglass	
268	.CSI	Idle Noise	28-3
104	.APM	Keybutton Stud — On/Off/Tab	
267	.APM	Linecord B/M	
52	.CSI	Linecord, Switch And Motor Lead Routing	28-2
389	.CSI	Machine Idle Noise	28-3
501	.CEM	Electrical Safety Precautions	
454	.CSI	Motor And Drive Double Insulation System	30-6
122	.CSI	Motor And Vent Grill — Redesigned	29-4
	.CSI	Motor Binds	29-6
	.CSI	Motor Clutch Springs — Tension	28-7
234	.APM	Motor Clutch — Wider Pawl Surface	
	.CSI	Motor Heat	28-4
418	.CEM	Motor Label	
264	.APM	Motor Mounting Bracket	
134	.APM	Motor Mounting Bracket — Overhead Wires	
	.CSI	Motor Noise — Worn Pulley Bushing	28-8
436	.CSI	Motor Pawl Asm. — Washer Added	30-4
	.CSI	Motor Pulley And Belt Wear	28-8
405	.CSI	Motor Pulley And Pawls — Defective	29-7
165	.CSI	Motor Replacement Procedure	27-4
	.CSI	Motor Shaft — Spiral Groove	28-6
378	.CSI	Motors — Longer Shafts	29-5
388	.PNM	Motors — Mounts	
	.CSI	Motor — Thermal Protected	28-1
439	.CSI	Motor Vent Grill Extension — Breaks	15-4
338	.CSI	Stalling During Corrections	13-2
	.CSI	Static Sparks	28-5
341	.APM	Switch Bracket — Redesigned	
239	.CSI	Switch Wires Loose — Quick Wire Switch	29-1
423	.CSI	Transformer Housing And Line Cord Plate — Wire Tie	30-2

CEM No.	Current Pub.	Subject	CSI Page/Item
472.	.CEM	Transformer Motor — "Selectric" III. . . . .	
437.	.CSI	Transformer Replacement — Wire Routing . . . . .	30-5
326.	.APM	Vent Grill And Platen Knobs — Black 8XX . . . . .	
<b>OPERATIONAL CONTROL</b>			
302.	.APM	Backspace Cam Follower (SP) — Strengthened . . . . .	
70.	.CSI	Cam Assembly Setscrew — Loosening . . . . .	32-2
357.	.APM	Cam Follower Oil Wick . . . . .	
301.	.SM	Cam Follower Replacement — Procedure . . . . .	
319.	.SM	Cam Follower Roller — Field Replacement . . . . .	
240.	.CSI	Cam Not Releasing . . . . .	31-7
	.CSI	Cam Pawl Installation . . . . .	31-4
108.	.CSI	Cam Pawl Spring Installation . . . . .	31-5
488.	.CEM	Carrier Return Operational Cam Pawl — Defective . . . . .	33
	.CSI	Check Pawl Spring Installation . . . . .	32-1
251.	.CSI	Extra Operations — Unwanted . . . . .	31-2
372.	.APM	Index Multiplying Lever Mtg. Stud B/M . . . . .	
	.SM	Interposer Height Adjustment . . . . .	
158.	.CSI	Interposer Latch — Burr . . . . .	31-1
	.CSI	Interposer Latch Replacement . . . . .	31-3
351.	.CSI	Interposer Restoring Bail Retainers . . . . .	32-7
345.	.CSI	Latch Wheel — Wearing . . . . .	32-6
431.	.CEM	Multiplying Lever Mounting Stud B/M . . . . .	
370.	.APM	Operational Interposer Restoring Bail — Redesigned . . . . .	
	.SM	Operational Shaft Removal Technique . . . . .	
434.	.CEM	Operational Shaft Support — Index Motion . . . . .	
289.	.CSI	Operational Shaft Support — New . . . . .	32-3
	.CSI	Pinion Wear . . . . .	31-8
	.CSI	Torque Limiter And Tab Governor — Adjustment . . . . .	32-5
362.	.CSI	Torque Limiter Arbor — Defective . . . . .	33-1
421.	.CSI	Torque Limiter Hub And Spring Clamp — Redesigned . . . . .	33-3
379.	.CSI	Torque Limiter Hubs — Defective . . . . .	33-2
461.	.CEM	Torque Limiter Hub — Defective . . . . .	
	.CSI	Torque Limiter Lubrication . . . . .	32-4
<b>PACKING</b>			
389.	.CSI	Motors, Shipping Bumper . . . . .	28-3
<b>PAPER FEED</b>			
127.	.APM	"A" Frame Paper Feed — Announced . . . . .	
191.	.CSI	"A" Frame — Removal And Conversion . . . . .	33-7
465.	.CSI	"A" Frame Replacement On Pre-Eccentric Overthrow Stop Machines . . . . .	33-7
280.	.APM	Anchor Rod Bushing — Pinfeed — Polyester Covers — 7XX . . . . .	
327.	.APM	Cardholder Bracket — Universal (Noncorrecting) . . . . .	
271.	.APM	Cardholder, D-Shaped — Correcting . . . . .	
250.	.APM	Cardholder, Material Changed — Correcting . . . . .	
230.	.APM	Cardholder Popping Out, Correcting — Dimples Added . . . . .	
220.	.APM	Cardholder — Universal 10P And 12P . . . . .	
	.CSI	Continuous Forms — Lateral Control . . . . .	34-6
473.	.CEM	Detent Arm And Roller 54T — Redesigned . . . . .	
	.CSI	Endless Forms . . . . .	34-5
	.CSI	Front Feed Roll Adjusting Screw Wrench . . . . .	1-2
282.	.APM	Handicapped Paper Knob . . . . .	
309.	.CSI	Linespacing Erratic — Pinfeed Platen . . . . .	35-3
278.	.APM	Page End Indicator — New Bias Spring . . . . .	
297.	.CSI	Paper Bail Arm And Platen Knob Screw — Loose . . . . .	34-8
404.	.CSI	Paper Bail Arm Screws — Redesigned . . . . .	36-3
409.	.CSI	Paper Bail Arm Spring — Incorrect . . . . .	36-2
359.	.CSI	Paper Bail Arms — Universal . . . . .	35-2
210.	.CSI	Paper Bail — Twisted . . . . .	34-2
485.	.CEM	Paper Release Lever — Redesigned . . . . .	
	.CSI	Pinfeed Core Key . . . . .	34-3
105.	.CSI	Pinfeed Core — Level 2 . . . . .	34-4
390.	.CSI	Pinfeed Platen — "D" Shaped Pins . . . . .	35-5
59.	.APM	Pinfeed Platen — Level 2 (140 Pins) . . . . .	
489.	.CEM	Pinfeed Platen Pin — Redesigned . . . . .	
447.	.CEM	Pinfeed Platen Support B/M . . . . .	
288.	.APM	Pinwheel Assemblies — High Lift Cam . . . . .	
164.	.APM	Pinwheel Assemblies — Plastic Pins . . . . .	
151.	.APM	Pinwheel, Platen Core Key Larger . . . . .	
126.	.APM	Platen Bushing — Oversize Available . . . . .	
366.	.CSI	Platen Court Reporting — Identification . . . . .	35-4
	.CSI	Platen Damage . . . . .	33-6
453.	.CSI	Platen Detent — Interference . . . . .	36-4
377.	.CSI	Platen Knobs . . . . .	36-1
287.	.APM	Platen Knobs And Vent Grills — Black 7XX . . . . .	

CEM No.	Current Pub.	Subject	CSI Page/Item
326.	.APM	.Platen Knobs And Vent Grills — Black 8XX.	
...	.CSI	.Platen Latch Adjustment.	33-4
210.	.CSI	.Platen Removal — Correcting "Selective"	34-1
...	.CSI	.Platen Substitution On 8X3 Machines	35-6
...	.CSI	.Platen Walks Out Of Latches — Bushings Bind	33-5
492.	.CEM	.Platen Variable — Engagement	
205.	.APM	.Print Shield — Correcting	
1.	.CSI	.Print Shield — Non-Correcting, Removable	34-1
353.	.CSI	.Soft Feed Rolls — Marking Original	35-1
<b>PINFEEED PLATEN</b>			
(See Paper Feed)			
<b>RIBBON CASSETTE</b>			
481.	.CEM	.Announcement/Discontinuance — IBM "Selective" III.	
482.	.CEM	.Announcement — IBM 210 Correctable Ribbon Cassette — IBM 800T — III Ribbon Cassette.	
486.	.CEM	.Selective III Ribbon Cassette — Noise	
493.	.CEM	.APM Correction — Ribbon Cassette	
<b>PLATEN</b>			
(See Paper Feed)			
<b>RIBBON, FABRIC</b>			
435.	.CSI	.Fabric Ribbon Reverse Failures — Plate	37-9
502.	.CEM	.Lift Guide — Fabric Ribbon — Improved	
...	.CSI	.Lift Guide Interference.	37-10
...	.CSI	.Load Lever — Excessive Motion.	37-6
...	.CSI	.Ratchet Detent Lever — Redesigned	37-7
...	.CSI	.Reverse Failure — Dimple	37-8
...	.CSI	.Reverse Failures — Brake Tension.	37-4
...	.CSI	.Reverse Failures — Lift Lever Interference.	37-1
...	.CSI	.Reverse Failures — Trigger Bind.	37-3
...	.CSI	.Reverse Interposer Spring Tension	37-2
...	.CSI	.Ribbon Tracking	37-5
182.	.APM	.Selective Ribbon To Fabric Ribbon — Parts.	
<b>RIBBON, FILM</b>			
...	.CSI	.Feed And Detent Cam Identification.	38-4
...	.CSI	.Feed Failures	38-2
...	.CSI	.Film And Fabric Ribbon Cam Follower Compatibility	38-5
...	.CSI	.Film Ribbon Changes.	38-3
...	.CSI	.Lift Link Spring — Fabric To Film Change	38-6
...	.CSI	.Ribbon Folding — Tracking Problems	38-1
...	.CSI	.Shock Spring Adjustment	38-2
111.	.APM	.Stencil Lever — Spring Washer.	
<b>RIBBON, SELECTIVE</b>			
300.	.SM	.Feed Gear Adjustment.	
229.	.APM	.Feed Gear — Polyester	
146.	.APM	.Feed Gear — Two Piece	
375.	.CSI	.Flaking And/Or Excessive Ribbon Dust	40-4
214.	.CSI	.Guard — Selective Ribbon	39-6
399.	.PNM	.Left-Hand Ribbon Lift Guide — Level 1	
275.	.CSI	.Lift And Tracking Failures — Soft Cams	39-5
141.	.APM	.Lift Cam Follower Roller — Diameter Increased	
120.	.APM	.Lift Control Lever Spring — Torsion Spring	
229.	.CSI	.Lift Control Lever Stud — Loose	39-3
294.	.CSI	.Lift Control Lever Stud — Wear.	39-4
190.	.APM	.Lift Guides — Redesigned	
269.	.CSI	.Load Lever Spring — Redesigned	40-1
143.	.CSI	.Print Quality — Tech III	38-1
304.	.CSI	.Print Quality — Overinking And/Or Fill-In.	40-3
483.	.CEM	.Ribbon Feed Cam Follower Asm.	
410.	.CSI	.Ribbon Lift Arm — Stripped Screw.	41-1
125.	.CSI	.Ribbon Lift Failures	39-2
180.	.APM	.Ribbon Lift Parts — Redesigned.	
320.	.CSI	.Selective Ribbon — Carrier Buffer	7-3
402.	.CSI	.Selective Ribbon Mech. — Feed Failures Ribbon Wrapping	41-2
299.	.CSI	.Spread Plate — Redesigned.	39-7
254.	.CSI	.Stencil Lever — Redesigned Selective Ribbon	39-8
259.	.APM	.Stencil Lever — Stop Lug Added	
121.	.APM	.Wobbler Bellcrank — Notch Removed	
360.	.CSI	.Wobbler Spring — Removed	40-2

CEM No.	Current Pub.	Subject	CSI Page/Item
<b>SELECTION</b>			
500.	.CEM.	Automated Selection Adjustment System . . .	
371.	.CSI.	Balance Arm — Solid — Conversion . . .	45-2
	.CSI.	Changing Tilt Adjustments . . .	45-3
416.	.CEM.	Check Pawl, Spring, Stud And Tab Keylever — Redesigned . . .	
	.SM.	Cycle Clutch Adjustment . . .	
	.SM.	Cycle Clutch Adjustment Procedure . . .	
	.CSI.	Cycle Clutch — Extra Cycles . . .	44-4
138.	.APM.	Cycle Clutch, Latch Pawl — Adjustment . . .	
	.CSI.	Cycle Clutch Pulley — Replacement . . .	44-1
	.CSI.	Cycle Clutch Restoring — Adjustment . . .	44-5
	.CSI.	Cycle Clutch Slippage — Diagnostic Aid . . .	44-2
497.	.CEM.	Cycle Clutch Spring — Defective . . .	
457.	.CSI.	Cycle Clutch Spring — Redesigned . . .	45-6
	.CSI.	Cycle Clutch Spring Wear . . .	44-3
211.	.CSI.	Cycle Shaft Cams — Loose . . .	44-6
94.	.APM.	Cycle Shaft Check Pawl — Redesigned . . .	
	.CSI.	Differential Bracket — Loose . . .	43-11
227.	.APM.	Differential Bracket — Replaceable Studs . . .	
85.	.CSI.	Dynamic Half Cycle Tool . . .	
	.SM.	Fine Timing — Adjustment . . .	
	.CSI.	Idler Gear, Upper — Backlash Adjustment . . .	45-1
	.CSI.	Negative 5 — Bail Latch Adjustment . . .	43-12
	.CSI.	Popping Selector Latches . . .	42-13
446.	.CSI.	Replacing Broken Selector Latch Links . . .	45-10
445.	.CSI.	Rotate Bellcrank Stud — Installation . . .	45-9
	.SM.	Rotate Link Adjustment . . .	
381.	.SM.	Rotate Selection Adjusting Tool (P/N 9900633) . . .	
	.CSI.	Rotate Tape Breakage — Bad Pulley . . .	42-2
	.CSI.	Rotate Tape Breakage — Diagnostic Aid . . .	42-2
	.CSI.	Rotate Tape Installation . . .	42-4
	.SM.	Rotate Tape Replacement . . .	
442.	.CSI.	Rotate Tape Replacement — Homing Changes . . .	45-8
	.CSI.	Rotate Tape XX5 on XX1, XX3 . . .	43-3
117.	.CSI.	Rotate Tape "T" Lifting Out Of Pulley . . .	43-1
152.	.APM.	Selector Latch Interposer And Bail — Redesigned . . .	
	.CSI.	Selector Latch Link — Replacement . . .	45-10
224.	.APM.	Skirt Clearance — Defective Detent Cam . . .	
	.CSI.	Tape Installation Pre Gear Tilt . . .	43-2
	.CSI.	Tilt Detent Entry — Adjustment . . .	43-8
112.	.APM.	Tilt Detent Guide Screw — Shortened . . .	
471.	.CEM.	Tilt Pulley Bushing Breaking . . .	
	.CSI.	Tilt Pulley (LH) Stud Wear . . .	43-10
	.CSI.	Tilt Pulley Spring . . .	43-9
	.CSI.	Tilt Tape Breakage — Machine Check . . .	42-2
	.SM.	Tilt Tape Replacement . . .	
406.	.CSI.	Tilt Tapes — Labels Incorrect . . .	45-4
	.CSI.	Timing Adjustments . . .	43-6
	.CSI.	Timing Problems . . .	43-7
441.	.CSI.	Two Piece Rotate Arm — Redesigned . . .	45-7
	.CSI.	Typehead Homing . . .	43-5
438.	.APM.	Upper Idler Gear Bushing — Redesigned . . .	
429.	.CSI.	Weak Cycle Clutch Drive/Contaminated Lubricant . . .	45-5
<b>SHIFT</b>			
	.CSI.	Backup Roller, Cam — Adjustment Check . . .	46-3
273.	.APM.	Cam, 8XX — Sintered Iron . . .	
451.	.CSI.	Carrier Return Unlatching Link — Interference . . .	11-3
235.	.CSI.	Detent Spring — Plastic Cam . . .	46-6
124.	.APM.	Detent Stud, Replacement — Stripped Frame . . .	
145.	.CSI.	Ratchet — Identification . . .	46-5
499.	.CSI.	Release Link — Incompatibility . . .	46-2
349.	.CSI.	Shift Arm Adjusting Screw — Recon Machines . . .	46-7
130.	.APM.	Shift Arm — One Piece Stamped . . .	
217.	.APM.	Shift Arm Pulley — Squeaking . . .	
499.	.CEM.	Shift Arm Pulley Tape Guard . . .	
169.	.APM.	Shift Arm Roller — "C" Clip Stud . . .	
252.	.CSI.	Shift Arm Roller Wear . . .	46-4
363.	.APM.	Shift Arm — Universal . . .	
167.	.APM.	Shift Bearing Plate — Backup Roller Eliminated . . .	
	.CSI.	Shift Bearing Retainer Plate — Level Difference . . .	46-8
	.SM.	Shift Drive — Adjustment Check . . .	
	.CSI.	Shift Spring — Adjustment . . .	46-1

CEM No.	Current Pub.	Subject	CSI Page/Item
<b>SOUND REDUCTION</b>			
393.	.CSI . . .	Acoustical Hood Seal — Redesigned . . . . .	47-3
450.	.CSI . . .	"Selectric" III Sound Reduction — B/M . . . . .	47-5
330.	.CSI . . .	Steel Membrane Support — Changed . . . . .	47-7
475.	.CEM . . .	Top Cover Jammed — Sound Reduction Machines. . . . .	
<b>SPACEBAR</b>			
. . . . .	.CSI . . .	Failure To Release — Release Lever Bite. . . . .	47-1
. . . . .	.CSI . . .	Failure — Trigger Restoring . . . . .	47-7
. . . . .	.CSI . . .	Interlock Intermittent Or Inoperative . . . . .	47-9
. . . . .	.CSI . . .	Intermittent Failures . . . . .	47-8
. . . . .	.CSI . . .	Interposer Spring Installation . . . . .	47-12
. . . . .	.CSI . . .	Latch Spring Installation. . . . .	31-6
. . . . .	.CSI . . .	Spacebar Binds . . . . .	47-10
73.	.APM . . .	Spacebar Keybutton — Spring Loaded . . . . .	
. . . . .	.CSI . . .	Spacebar Stiff — Burrs . . . . .	47-11
. . . . .	.CSI . . .	Space To Print B/M — Early Machines . . . . .	48-1
<b>STROKE COUNTER</b>			
427.	.CEM . . .	Stroke Counter — Redesigned . . . . .	
<b>TAB</b>			
395.	.SM . . .	Dual Transport Conversion . . . . .	
208.	.APM . . .	Dual Transport Cord System . . . . .	
383.	.CSI . . .	Escapement Rack — Soft. . . . .	19-4
163.	.CSI . . .	Keylever Linelock — Field B/M. . . . .	48-4
. . . . .	.CSI . . .	Mainspring Identification . . . . .	48-3
335.	.APM . . .	Single Pitch — Rotary Backspace — New. . . . .	
415.	.CSI . . .	Tab Lever Washer/Clip Added. . . . .	49-3
107.	.APM . . .	Tab Lever And Pawl — Overthrow Stop Eliminated. . . . .	
337.	.CSI . . .	Tab Lever (RB/S) Spacer Binding. . . . .	49-2
168.	.APM . . .	Tab Lever Spacer (DP) — Diameter Reduced . . . . .	
131.	.APM . . .	Tab Mechanism (DP) — Redesigned. . . . .	
183.	.APM . . .	Tab Rack (DP) — Friction Fit . . . . .	
84.	.APM . . .	Tab Rack, Friction Fit — Replaced Silicone . . . . .	
189.	.APM . . .	Tab Rack — "Snap In" Studs . . . . .	
373.	.CSI . . .	Tab Set And Clear Bracket. . . . .	48-5
106.	.APM . . .	Tab Stops Clearing — Friction Fit Racks. . . . .	
. . . . .	.CSI . . .	Torque Bar Binding. . . . .	48-2
376.	.CSI . . .	Transport Cord Pulley Assemblies Redesigned. . . . .	49-1
<b>TAB (DUAL PITCH)</b>			
479.	.CEM . . .	Escapement Bracket (RB/S) Defective . . . . .	
376.	.CSI . . .	Transport Cord Pulley Assemblies Redesigned. . . . .	49-1
<b>TYPE ELEMENTS</b>			
(See Applications)			
(See Carrier And Rocker)			

CEM No.	Current Pub.	Subject	CSI Page/Item

CEM No.	Current Pub.	Subject	CSI Page/Item